General Environmental Incident Summary

Incident: 3586 Date/Time Notice: 12/19/2014 16:30 DEM Incident No:

Responsible Party: Agrekko

Date Incident: 12/19/2014 Time Incident: 14:50 Duration:

County: Dunn Twp: 147 Rng: 93 Sec: 15 Qtr: NW NW

Lat: 47.55828 Long: -102.51970 Method: Navigation quality GPS

Location Description: Boychief USA 11-15H

From Hwy 22 turn east onto BIA 14 travel 4.7 miles to BIA 17.

* Turn right (southeast), travel 8.5 miles to lease road.

* Turn left (north), travel ~ 0.2 miles to location.

Submitted By: Tonya Woolery Affiliation: Marathon Oil

Address: 3172 Hwy 22 N

City: Dickinson State: ND Zip: 58601

Received By:

Contact Person: Daryl Enget

Hwy 22 N

Dickinson, ND 58601

Distance Nearest Occupied Building: Release Contained: Yes

Type of Incident: Tank Overflow

Description of Released Contaminant: Diesel

Volume Spilled: 123.00 gallons Aq Related: No

EPA Extremely Hazardous Substance: No Reported to NRC: Unknown

Cause of Incident:

Contractor was transferring diesel from one tank to another and due to inattention the transfer tank overflowed.

Risk Evaluation:

No risk of explosive atmosphere or immediate health risks.

of Fatalities: 0 # of Injuries: 0 Affected Medium: 03 - soil

Potential Environmental Impacts:

Impacts to surface or ground water are minimal. All fluid remained on location.

Action Taken or Planned:

Flow of fuel was stopped. Spill contractor is enroute for spill cleanup.

Wastes Disposal Location: All wastes are the responsibility of the contractor and will be disposed of at an approved facility.

Friday, January 27, 2017 Page 1 of 2

Agencies Involved:

Updates

Date: 12/22/2014 Status: Reviewed - Assigned to Other Agency Author: Martin, Russell

Updated Volume:

Notes:

Release, due to tank overflow, remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.

Friday, January 27, 2017 Page 2 of 2